

SUBJECT**New Fuse Requirements For Pacbrake
Remote Air Compressor****MODEL NUMBER****C18022 Compressor / Manufacturer Model 27520**

Some customers have experienced failure of the 20 amp inline fuse used to operate our remote air compressor. The compressor may experience start-up amperage exceeding 20 amps causing the fuse to blow.

Our compressor manufacturer has advised us that we can increase the amperage of the fuse to 30 amps. Customers who experience a failure of the 20 amp fuse should install a 30 amp before troubleshooting or replacing the compressor.

Please do not increase the fuse amperage on a model of compressor that differs from the one shown in the photo below.



For More Information Contact **Pacbrake** Service at **1 800 663 0096**