

CAUTION!

IMPORTANT INFORMATION

Navistar is now using a new turbocharger called EVRT (electronic variable rate turbocharger) on DT466, DT570 and HT570 engines.

EXHAUST BRAKES MUST NOT BE INSTALLED ON ENGINES EQUIPPED WITH EVRT TURBOCHARGERS.

To determine if your engine has an EVRT turbocharger, check the engine serial number:

DT466 engines with serial number starting with 466DM2U

DT570 engines with serial number 570DM2U

HT570 engines with serial number 570DM2U

All these engines are equipped with EVRT turbochargers.

Another way to determine if the engine is equipped with an EVRT is to look below the turbocharger for an electric motor attached to the bottom of the turbo.

Please do not install an exhaust brake on engines equipped with an EVRT turbocharger until further notice.

Pacbrake Service

800 663 0096 - WWW.PACBRAKE.COM